

Shapping Machine



**Cone Pulley Type Shaping Machine
MODEL SS 30**



**All Geared Shaping Machine
MODEL PSG-600**

▶ Standard Accessories

- Swivelling Vice
- Crank Handle
- Motor Pulley
- Motor Base

▶ Optional Accessories

- Electric Motor, Swith Starter
- Key Way cutting attachment
- Automatic tool lifting Attachment
- All geared type
- Automatic lubrication arrangement
- Stroke adjustment indicator Base

SPECIFICATION

MODEL	SS12	SS18	SS24	SS30	SS36	SS40
Maximum working stroke	14"	20"	26"	32"	38"	42"
Length of ram without tool slide	30"	40"	53"	60"	66"	75"
Ram bearing in column	20"	26"	31"	37"	41"	44"
Ram bearing width	7.5"	10.5"	12"	12.5"	12.5"	14"
Tool Slide Traverse	5"	6"	8"	9"	10"	11"
Maximum distance from table to ram	14"	15"	16"	18"	20"	24"
Maximum distance from table to ram	2"	2"	2"	2"	2"	3"
Horizontal traverse of the table	16"	20"	26"	30"	32"	36"
No of speed	3	3	4	4	4	4
Length and width of cross slide	25"*10.5"	31"*11"	38"*12"	43"*12.5"	46"*12.5"	51"*15"
Top clamping surface of table	14"*11"	18.5"*12"	25"*15"	31"*16"	37"*18.5"	40"*20.5"
Size of base plate	40"*16.5"	50"*22"	64"*23"	76"*24"	82"*26"	90"*30"
Power required	1 H.P.	2 H.P.	3 H.P.	5 H.P.	5 H.P.	7.5 H.P.
Approximate net weight	800 kg.	1200 kg.	1800 kg.	2300 kg.	3200 kg.	4000 kg.