

# ARC Welding Machine



ARC WELDING 200 AMPS



ARC WELDING 300 AMPS



ARC WELDING 400 AMPS

# Manual / Hand Plasma Cutting Machine

Particulars	Inverter Plasma Cutters			
Model	CUT40	CUT60 3P	CUT100 I	
Input Voltage (V)	220V ±15%	380V ±15%	380V ±15%	
Phase	1	3	3	
Frequency (HZ)	50 / 60	50 / 60	50 / 60	
Rated Input (A)	30	12	23.1	
No-load Voltage (V)	230	240	268	
Output Current Range (A)	15-40	20-60	20-100	
Base Material	Plate Thickness (mm)	Current Range (A)	Air Pressure	Applicable Model
Carbon Steel, Stainless Steel, Low-alloy Steel	0.8-15.0	20-40	3-4	CUT40
	0.8-25.0	20-60	3-4	CUT60
	0.8-40.0	20-100	3-4	CUT100

